

SPENCER J. COX

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed

FPAT

Report Date: 07/15/2014						
Mine Name: Bingham Canyon Mine	Permit Number:	M/035/0002	Mine Status:	Active		
Operator Name: Rio Tinto - Kennecott Utah Copper	Inspection Date:	August 21, 2013	Permit Fees:	Paid		
Inspector(s): L Heppler, A Abate, T Nicolaysen	Inspection Time:	8:00 AM	Bond Amount:			
Attendee(s): T Lindsay, T Heaton	Weather:	Sunny, Dry	Bond Escalation:			
Inspection Purpose: Routine annual inspection			Prior Inspection:	May10, 2012		
Conclusions and Recommendations OGM recommends working on biodiversity of veget submitted with bond calculation. OGM to contin				to be		

	Elements of Inspection	Evaluated & Commented	Enforcement			
1.	Permits, Revisions, Transfer, Bonds					
	Permit fee is up to date, reclamation bond is a Board Contract					
2.	Public Safety (shafts, adits, trash, signs, highwalls)					
	Mine site is acessed through a paved roadand a full time manned secure entrance. No trash was noted onsite. Highwalls are internal and don't affect public safety					
3.	Protection of Drainages/Erosion Control					
	No erosional problems were noted during inspection, several large sediment basins at the toe of the East and South dumps were visited andthe basins were properly maintained					
4.	Deleterious Material					
	Fuel was properly contained. Kennecott has ongoing South Area cleanup program with principal oversite by DERR					
5.	Roads (maintenance, surfacing, dust control, safety)					
	Roads were well maintained and in good condition with water for dust suppression	well maintained and in good condition with water for dust suppression				
6.	Reclamation					
	The throat of Bingham Canyon, is undergoing concurrent reclamation	oat of Bingham Canyon, is undergoing concurrent reclamation				
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)					
	Upper dumps in the throat of Bingham Canyon are being pushed down to 2.5H:1Vin preparation for topsoil. Old railroad grade has been nicely recountoured and looks great. See attached photos					
8.	Soils					
	No soil stockpiles are noted at the time of inspection. Soil is salvaged and placed directly onto dumps.					
9.	Revegetation					
	Vegetation is dominantly a variety of grasses. Railroad grade seeded in the fall of 2013					
10.	Other .					
	This line is intentionally left blank					

Inspector's Signature:

CC: Chris Kaiser - Kennecott

 $File: \ / nrwogmfs 1/OGM/GROUPS/MINERALS/WP/M035-SaltLake/M0350002-Bingham Pit/inspections/INSP-08212013.pdf$



Mine: M/035/0002 Inspected: August 21, 2013



Railroad grade reclamation



Railroad grade reclamation



Railroad grade reclamation




Railroad grade reclamation




Mine: M/035/0002 Inspected: August 21, 2013



Overview of mine site - top os east dumps



Overview of mine site - top of south dumps



Overview of mine site - top of north side dumps



Overview of mine site - top of throat of Bingham Canyon dumps and 2013 pit slide

